

**Table 4-16
GDOT 2006 Bridge Inspection Report, Bridge Structures Requiring Posting of Weight Limits¹**

Structure ID	Location ID	Location	Issue
063-0076-0	063-09097M-002.92N	CR 1344, Valley Hill Road over Flint River	Insufficient shear capacity of concrete superstructure
063-0077-0	063-09100M-001.00ES	CR 392, Upper Riverdale Road over Flint River	Insufficient shear capacity of concrete superstructure
063-0081-0	063-09108M-000.83E	CR 1342, Battlecreek Road over Jestors Creek	Insufficient shear capacity of concrete superstructure
063-0086-0	063-09110M-007.65E	CR 1351, Rex Road over Big Cotton Indian Creek	Low load carrying capacity
063-5004-0	063-00126X-000.22N	CR 126, E. Conley Road over Conley Creek	Substructure in poor condition due to timber decay. Posting required due to poor cap support at bent
063-5010-0	063-00299X-000.48S	CR 299, West Lee's Mill Road over Flint River Tributary	Insufficient capacity of timber cap at south abutment. Structure in serious condition and is located on a school bus route. Replace cap.
063-5025-0	063-00800X-000.14E	CS 800, Huie Road over Jestors Creek Tributary	Insufficient flexural capacity of steel superstructure.
063-5029-0	063-01340X-000.66N	CR 1340, Conkle Road over Reeves Creek	Insufficient load carrying capacity of timber substructure piles. Piles either too small or signs of advanced internal decay.